







i






i



i



i




⚠ WARNING		WARNING! Stored Energy Hazard: The arm mechanism is under tension and will move up rapidly, on its own, as soon as attached equipment is removed. For this reason, DO NOT remove equipment unless the arm has been moved to the highest position! Failure to follow this instruction may result in serious personal injury and/or equipment damage!

ZG2-w/DS-50-0024 Rev 2

zgonic

zgz



© Copyright 2023

