









## 

## WARNING! Stored Energy Hazard:

The arm mechanism is under tension and will move up rapidly, on its own, as soon as attached equipment is removed. For this reason, **DO NOT** remove equipment unless the arm has been moved to the highest position! Failure to follow this instruction may result in serious personal injury and/or equipment damage!

ZG1-w/DS-50-0022 Rev 4

zgonic

## ZG1





